

Oil Field Environmental Incident Summary

Incident: 20151014181707 **Date/Time of Notice:** 10/14/2015 18:17
Responsible Party: FIDELITY EXPLORATION & PRODUCTION COMPANY
Well Operator: FIDELITY EXPLORATION & PRODUCTION COMPANY
Well Name: PARKER 29-32H
Field Name: GREEN RIVER **Well File #:** 20694
Date Incident: 10/14/2015 **Time Incident:** 09:30 **Facility ID Number:**
County: STARK **Twp:** 140 **Rng:** 98 **Sec:** 29 **Qtr:**
Location Description:

Submitted By: Edward Pottorff **Received By:**
Contact Person: Edward Pottorff
1801 CALIFORNIA STREET
SUITE 2500
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other	15	Barrels	10	Barrels	13.5	barrels
-------	----	---------	----	---------	------	---------

Description of Other Released Contaminant:

Emulsion from treater

Inspected: **Written Report Received:** 10/26/2015 **Clean Up Concluded:** 10/16/2015

Risk Evaluation:

No immediate risks identified

Areal Extent:

Potential Environmental Impacts:

Surface soils on the facility pad just outside the containment berm were impacted as were the gravel and soils within the containment berm.

Action Taken or Planned:

A VAC truck was mobilized immediately to collect the free liquids from the spill and put them back into the tank and treater system. The affected gravel inside the containment berm will be pressure washed, these fluids will then be collected with the VAC truck and will either be put back into the treater system or hauled to a licensed, off-site disposal facility. Affected soils on the facility pad outside the containment berm and possibly within the berm will be excavated and hauled off-site to a permitted disposal facility. Any removed soils will be replaced with clean soils, as needed. The fire tube gasket will be repaired or replaced before the well is put back into service.

Wastes Disposal Location:***Agencies Involved:******Updates***

Date: 10/15/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Tintes Schiwal, Emily

Updated Oil Volume:***Updated Salt Water Volume:******Updated Other Volume:******Updated Other Contaminant******Notes:***

The release was contained to the facility site. NDIC Oil & Gas retains oversight.